

## BUILDING SAFETY CERTIFICATE

No. 8146


Dated:

Certified that the existing building of The Donush Siangshai Educational Trust (name of the building or premises) at Lad Langkyrding, Nongmenson, Shillong (address) comprised of No basement(s) and G+4, G+3 & G+1 floors (upper floors) owned/occupied by BDW International School, Nongmenson (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of MUDA, Shillong (Name of Department/ Govt.) on 28<sup>th</sup> February 2022 (date of inspection) in the presence of Shri. Donush Siangshai, Chairman, Shillong (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes XI (XI/ XII) with effect from 4<sup>th</sup> March 2022 for a period of 80 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The Building was completed under the supervision of Ace Group
2. Architects (P) Ltd. Bangalore, Regn. No. HUDA/LTF/2018/FM/23. Hence
3. this certificate is based on their completion report.
- 4.

Issued on 15/11/22 at Shillong by

\* Strike out whichever is not applicable.

Signature with Seal : 

Name : \_\_\_\_\_

Designation : Assistant Engineer

Name & Address of Department/Office: Urban Development Authority

(Assistant Engineer & above officer of concerned Govt. Department only)

**Note:** This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.